

316233902

Attention Installer:

The connector on this replacement probe may be different from the original. If it is, cut the connector off and splice the harness and probe wires together.

PN 5304475565