

8182793.

Notice to Installer:

⚠ WARNING

Electrical Shock Hazard

**Disconnect power before servicing.
Replace all parts and panels before
operating.
Failure to do so can result in death
or electrical shock.**



This new service motor you have received has an integrated motor shield by the connector. If the failed motor that is being replaced does not have this shield, then the shield that is attached to the tub needs to be removed to allow the clearance required for the new motor.

Notice pour l'installateur :

⚠ AVERTISSEMENT



Risque de choc électrique

Déconnecter la source de courant électrique avant l'entretien.

Replacer pièces et panneaux avant de faire la remise en marche.

Le non-respect de ces instructions peut causer un décès ou un choc électrique.

Le nouveau moteur que vous avez reçu pour remplacement comporte un élément de protection intégré près du connecteur. Si le moteur remplacé ne comporte pas cet élément de protection, l'élément de protection fixé à la cuve devra être enlevé pour que l'espace nécessaire pour le nouveau moteur soit disponible.