

Speeds	1
Volts	120
Amps	1.3
Rotation	CCWLE
RPM	3000
Amps at Free Air	0.45
Bearings	Ball
Diameter (In.)	3.3
Enclosure	Open
RPM at Free Air	3100
Static Pressure 0.1 in.	69
Static Pressure 0.2 in.	68
Static Pressure 0.3 in.	66
Static Pressure 0.4 in.	57
Static Pressure 0.5 in.	59
Static Pressure 0.7 in.	47
Static Pressure 0.8 in.	43
Motor Type	Shaded Pole
Frame	C Frame
Overload	Automatic
Phase	1
Hertz	60