





Instruction Sheet

16026420

Description: Roller Kit

Repair Part Number: LA-1008

Kit includes:

 Retaining Ring (qty 2) 25-7574	 Washer (qty 2) 25-7814	 Spacer (qty 1) 31001583	 Screw (qty 4) 25-7101	 Support Assy (qty 2) 53-0197	 Cylinder Roller (qty 2) 53-0163	 16026420 Instruction Sheet
--	--	---	---	---	---	--



WARNING


To avoid risk of electrical shock, personal injury or death; disconnect electrical power before servicing.

Procedure:

Install both cylinder rollers supplied in this kit at the same time.

The Spacer supplied in this kit (31001583) is to be used on the right rear Support Assembly only.

Note: Previously released kit contained two thinner washers. When stacked together they add up to the same thickness as the one provided in this kit.







Feuille d'instructions

16026420

Description : Trousse de galet

Pièce de rechange numéro : LA-1008

La trousse inclut :

 Anneau de retenue (qté 2) 25-7574	 Rondelle (qté 2) 25-7814	 Butée d'espacement (qté 1) 31001583	 Vis (qté 4) 25-7101	 Support (qté 2) 53-0197	 Cylindre de galet (qté 2) 53-0163	 16026420 Feuille d'instructions
---	--	---	---	--	---	---



AVERTISSEMENT

Pour éviter les risques de choc électrique, de blessures ou de mort, débrancher l'alimentation électrique avant d'effectuer l'entretien.

Étapes à suivre :

Installer en même temps les deux galets de cylindre fournis dans cette trousse.

La butée d'espacement fournie dans cette trousse (31001583) doit être utilisée sur le support arrière droit seulement.

Remarque : Les trousse précédentes contenaient des rondelles plus minces. Lorsqu'elles sont empilées ensemble, elles ont la même épaisseur que celle fournie dans cette trousse.

