

WH20X23194 Drive_motor_sub

ATTENTION SERVICE TECH

Contents:

WH20X23194	Drive_motor_sub	1 each
WH02X10212	Motor Washer	1 each
WH02X10213	Flange Bolt M8*35	1 each

YOU MUST USE THE NEW BOLT AND WASHER
WHEN YOU REPLACE THE MOTOR

The thread locking adhesive on the Bolt is permanently damaged when you remove the bolt from the tapped hole in the Motor Washer.

Discard both old Bolt & Motor Washer parts, and use the new ones to properly secure the new Motor to the tub.

February 2015