



WH49X10042 Agitator Coupling Replacement Kit Instructions



Due to a design change in the factory the old WH43X10009 agitator coupling has now superseded to the WH49X10042 kit consisting of a new coupling and a longer screw. The old coupling and screw should be discarded and replaced by the new coupling and longer screw. The new kit is backwards compatible for older models but the old parts should not be used for current models.

WH00X5549