

BETCOMotoMop[™] Operation Wallchart

Set Up

TIP: To ensure run time, charge battery after each use.

TIP: Never store in upright position with liquid in solution or recovery tanks.











Prepare For Operation

- Place solution tank back into MotoMop™
- Secure lid by closing with both hands
- Transport to area








Operation

- Adjust handle height for operator comfort
- Lower squeegee and Turn ON Power/Solution

TIP: FOR WET SPILLS; Turn ON Vacuum only (Power) for first pass, Take second pass with both Power and Solution ON.







Storage

After each use, rinse recovery tank by thoroughly flushing inside channels. Use maintenance brush provided to keep vac intake channel clear of debris. Wipe squeegee storage.













Maintenance

Scan QR code to view each MotoMop video.





Squeegee Maintenance and Replacement Blades





Changing the Brush











Changing Seals and Vac Seals